

EMBASSY FENCES AND BOLLARDS RE-PAINTING SCOPE OF WORK

There are following US Embassy metal items to be re-painted:

1. COMPOUND PERIMETER FENCE with 1250 sq. m total metal surface in green existing color.
2. INTERNAL DIVIDING FENCE from MCAC to the retaining wall with 120 sq. m total metal surface in black existing color.
3. INTERNAL DIVIDING FENCE from the Chancery to the compound perimeter fence with 130 sq. m total metal surface in black existing color.
4. EMBASSY PARKING LOT FENCE with 560 sq. m total metal surface in black existing color.
5. EMBASSY BOLLARDS with 250 Sq. m total metal surface in black green existing color.
6. EMBASSY CACs SLIDING DOORS with 120 Sq. m total surface in black existing color.

All that above shall be re-painted in GREEN, in 6005 according to RAL color chart. To be used already tested in the Embassy so called Expert Alkyd enamel paint manufactured by MEGACHIM Company.

All metal surfaces shall be first thoroughly cleaned with water soaked rag, then with an organic solvent.

All corroded metal parts shall be sandpapered before re-painting.

If the old color is black or black green, (2) layers of new paint shall be Implemented, otherwise - (1) layer of paint.

To be painted with rollers and brushes eventually. Don't use paint spays.

Notices shall be used for attention drawing and warning people for keeping clear of painted parts.

Time of painting of the CACs sliding doors and bollards shall be coordinated with the Facility engineer first.

End of Scope of Work