

U.S. Embassy  
686 Old Bagamoyo Road  
Dar Es Salaam, Tanzania  
August 18, 2014

REQUEST FOR QUOTATION for PR3590759 – Walkway Renovation 44 Laibon

Dear Vendor,

The Embassy of the United States of America invites you to submit your quotation for the products or services shown below.

Your quotation must be submitted by **1100 hours local time on September 19, 2014**.

A site visit has been scheduled for Tuesday, August 26, 2014 at 1200 hrs. (noon)

The electronic address for submission is [darprocurementbid@state.gov](mailto:darprocurementbid@state.gov).

- On the e-mail's subject line, state that the submission is for PR3590759 – Walkway Renovation 44 Laibon
- On your attached proforma, state that the proforma is for PR3590759 – Walkway Renovation 44 Laibon
- 

The US Government intends to purchase the lowest priced technically acceptable product or service.

All vendors receiving awards over \$25,000 must be registered in SAM.

We encourage all vendors which may bid either on this solicitation or in the future to start now and complete the SAM registration process. Registration will make the award process move much more smoothly and quickly. The registration process is not difficult, provided all instructions are followed carefully. Please see our Embassy Contract Opportunities web page for details or call us if you have questions

Any questions regarding this Request for Quotation must be directed to the Procurement Section +255-22-229-4138 during office hours.

Sincerely,

The Contracting Officer

# **U.S. Embassy**

## **PR 3590759 – Renovation Walkways 44**

Location 44 Laibon Renovations

### **BRICKED WALKWAYS**

1. The bricked walkway and driveway have to be redone. Both are showing considerable amounts of wear and tear.
2. Install pavers in front and stone in the back.

### **VERANDA REPAIRS**

1. Cover the veranda properly by building arched solid wall and use UPVC fittings for closing it up.
2. Put an additional AC on the veranda preferably Split unit 24,000 BTU.

### **BATHROOMS UPGRADE**

3(Three) bathrooms require an upgrade: Remove all existing wall tiles, all existing floor tiles, remove all ceramic fixtures, removal all previously applied wall and floor mortar and make a new application of wall and floor mortar. Remove all existing toilets, wash basins, wall mirrors, bathtubs, shower stalls, enclosures, removal all existing embedded pipes from the walls and provide with installation new IPC Pipes and connections to all new sanitary fixtures. Provide new LED Lighting from the ceilings in each bathroom. Provide new high CFM bathroom exhaust fans. Provide new high quality ceramic wall and floor tiles from CTM or RAK or other FM Approved sources. No Asian tiles will be acceptable. South African, Dubai manufactured or European manufactures will be accepted. Provide new wall mounted lighted mirror or light above mirror. Provide separate source of electrical power for the new bathroom exhaust fan. Provide two each electrical outlets near the new wall mirror above or next to the new ceramic wash basin. Replace all the electrical light fixtures in the Master bedroom Bathroom with ones that are brighter.

### **KITCHEN UPGRADE**

Kitchen upgrade: Remove all kitchen cabinets and counter tops first, remove all existing kitchen wall cabinets, then remove all existing wall tiles, all existing floor tiles, remove all piping fixtures to include drainage, remove all previously applied wall and floor mortar and make a new application of wall and floor mortar. Remove all existing embedded pipes from the walls and provide with installation new IPC Pipes and connections to all new faucets, connections etc. Provide new LED Lighting from the ceilings in each kitchen. Provide new high CFM exhaust fans. Provide new high quality ceramic wall and floor tiles from CTM or RAK or other FM Approved

sources. Provide new Granite Counter tops if old ones are not recyclable. No Asian tiles will be acceptable. South African, Dubai manufactured or European manufactures will be accepted. Provide separate source of electrical power for the new exhaust fan. Provide extra wall embedded electrical outlets. The existing sink and workspaces are too small and narrow.

#### GUARD HOUSE

Replace the Guard house with a larger proposed guard house that should be approximately 3.5 X 2.5 meters floor plan.

#### INTERIOR REPAINTING

Repair all Damaged parts and repaint the whole interior of the house using high quality wash and wear paint.