

## **1. SCOPE OF WORK SEISMIC EVALUATION AND STRUCTURAL MODIFICATIONS DESIGN USAID RESIDENCE.**

The purpose of this contract is to obtain a seismic evaluation and a structural design to modify the current seismic rating of the residence from Poor to Good. The residence is located on 14 Jose Antonio Polanco Billini Street, Arroyo Hondo in the city of Santo Domingo, Dominican Republic

The Contractor shall furnish all commodities, services, managerial, administrative, overhead and direct labor personnel to accomplish the work in this contract. Contractor employees shall be on site only for contractual duties and not for other purposes.

All standard services are to be delivered on regular, non-holiday weekdays unless specified otherwise in writing by the Contracting Officer's Representative (COR).

## **2. REFERENCES**

1.1.1 Seismic rating document.

2.1. General Requirements. These requirements apply to all work.

1.2.1 Except as otherwise specified, the contractor shall provide all labor, materials, services, tools, equipment, supervision, transportation and technical expertise needed to accomplish the work required by this specification.

1.3 Duties and Responsibilities.

1.3.1 All services shall be performed during regular working hours and days. Normal working hours are defined as 8:00 to 16:45 Monday to Friday, excluding local and U.S. holidays.

1.4 Types of services and Commodities

Services shall include the following work:

1.4.1 Perform seismic evaluation of residence

1.4.2 Revise blue prints provided by USG

1.4.3 Do all necessary data collection

1.4.4 If necessary do soil survey to determine correct correction of soil sliding

1.4.5 Create detailed structural design proposal to correct existing structural settlement and to change poor seismic rating to Good.